BID OPENING CERTIFICATION RECORD

Date of Bid Walk: $\frac{4-26-18}{}$ Due Date:	5-3-18 NBS#:
Address	PBE Amount
PUBLIC BODY ESTIMATE: 620 5. Summit	\$20,H40
PUBLIC BODY ESTIMATE:	(+.15) \$23,506
PUBLIC BODY ESTIMATE:	(15) \$17,374
PUBLIC BODY ESTIMATE:	
PUBLIC BODY ESTIMATE:	
PUBLIC BODY ESTIMATE:	
\times	BIDDERS
Address: Japer	Goodwill Schultz Stama yest
1. Le20 Summit 86,40	
2	(capring) (capring) ok low
3. Dm	Dry Dry
4.	5/10/18
4	
5	
6	<u> </u>
7	
8	
9	
10	
	ly opened and read aloud in the Neighborhood & Business Services
Office located at 600 E. Trade Street, Charlotte, NC Bids Opened By: Bids Witnessed By: Da	s Recorded By: Umanda Wood
Witnessed By: Da	nte: 5-3-18
Note: Responsive bids are those which fall within a range of 15	% above and 15% below the public body cost estimate. As a



Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

Property Details						
Address:	620 South Summit Ave		Owner:	Isabella Gastor	n	
Charlotte, NC 28208	Charlotte, NC 28208		Owner Phone:	Phone: Home: 605-6807		
Structure Type:	Single Unit		Program(s):	Healthy Homes		
Square Feet:	1200			Safe Home FY	2018	
Year Built:	1922					
Property Value:	159500					
Tax Parcel:	07102329					
Census Tract:				•		
Property Zone:	Council District 2					
Repairs					e de la companya de La companya de la co	
<u>Description</u>			į	Floor Room	<u>Exterior</u>	
Permits Required				GENER	AL REQUIREMENTS erior	
The contractor is respon	slble obtaining and paying for all perm	its required	. Said permits sh	nall include all iter	ms in this scope of work.	
		Bid Cost	·	х —	= (00)	
			Base	Quantity	Total Cost	
Portable Tollet	THE STATE OF THE S		tritization recording	GENERAL REQUIREME惟於erlor		
Provide temporary tollet	facilities from job start until approval o	f permanen	t facilities.			
		Bid Cost		х	= 120	
		•	Base	Quantity	Total Cost	
See Attached Lead Sco	ppe	· · 1. 1. 1. 1. 1	ege 1 de 1994 y 21 e dyse per e	GENERA	AL REQUIREMENTATION	
will be obtained as appro	ned in accordance with applicable regul opriate. Mecklenburg County requires b litting under general conducts. (4.0)					
	•	Bid Cost	•	X	= 14/300	
and the language of the language of the same	و المعادات و المعادي و المعادي و المعادات و	r et .3166rs 1	Base	Quantity	Total Cost	

2018 1

Work Specification

Vinyl Siding - Replace damaged siding at right of rear door.		EXTERIOR	Exterior
Danicas all deteriorated exterior VINYL SIDING components. Wrap home	with Tyvek vapo	r/ infiltration barrier.	Install vinyl clapboard
siding including corners, door and window trim to complete installation. Ow year warranty. (11.4)	ner's choice of s	siding color, exposur	e, and texture with 50
Bid Cost:		x - =	500
Bid Cost.	Base	Quantity	Total Cost
	-		
FRONT- Install Handrall and guardrail at steps/porch	/ Homes)	EXTERIOR	Exterior
Install code approved handrails. Handrall up steps, one side. Guard rail at porch landing, left,right & front.			. 4
		х=	2,500
Bid Cost:	Base	Quantity .	Total Cost
ALL Windows	زائمتم الامواردس والممسم المفد ودردووا ا	EXTERIOR	Exterior
WINDOWS ONLY Prep and paint all exterior WINDOW painted surfaces. Any panes of glass dispose all loose materials. Secure or replace all loose, broken, rotted or etc. prior to applying 25-year or better Low VOC paint. Owners choice of our Use care to protect all surfaces not intended for paint coverage.	leteriorated mate color. All work to	eriais. Caulk and fili i	ali cracks, voids, noies,
Bid Cost	: Base	Quantity	Total Cost
WOOD SASH REPLACEMENT WINDOWS - ONLY	and the first state to be seen to	nesia da meramo ^d e estada fista para 1996 e estado sobre a	pari s in the second marketing in the second
Replace the two (2) decayed Wood Window Sash ((4/1)) sets. Paint to n security bars. Field measure, order and install new Energy Star rated viny Insulate rough opening. Install new extension jambs, casing and sill as ne coated aluminum coll as needed. Repair all areas disturbed by removal ar damaged header, framing (to include king studs, jack studs etc.) sub-floor	i, double glazed eded, prime and id installation. T	LOw- E windows in paint, Exterior trim t his installation is to i	to be wrapped in PVC nclude repairing any
Bid Cost		x =	. (,800)
Did Good	Base	Quantity	Total Cost
Certification	e i i i i i i i i i i i i i i i i i i i	seed to be a seed of the seed	entro (i originali di la formati di la compania di La compania di la co
Contractor Name:		Total Cost	23,350
		_	212

Work Specification - City of Charlotte Housing & Neighborhood Services

2/19/2018

Item # Feature Date EXTERIOR - Side A thru Side D: Address gray concrete foundation

Scrape loose paint and re-paint

Internal COST ESTIMATE 620 S. Summit Ave.

2/16/2018

Cost Per Number Unit

copy into the Bid Sheet.

for that item in C5....items will:

Sheet, allow Fit Sheet on one page as below When printing, the Budget

Pages Settings Only print the active sheets Shrink the printout so that it fits on one page 喧喧 Collated 1,23 1,23 1,23 Print on Both Sides No Staples Portrait Orientation Normal Margins Left: 0.7" Right: 0.7" 85"×11" Letter (8.5° x117) Flip pages on long edge (۱) اة : Page Setup

replaced with newer wood which is 8 not-coated with lead-based paint) INTERIOR Room 1, Side D; white 9 wood freplace mantle and trim 10 the gray vinyl siding) EXTERIOR - Side A Entry; gray EXTERIOR - Side A thru Side D: EXTERIOR - Side C; exposed wood siding around electric panel INTERIOR - Side A thru Side D; INTERIOR - Throughout Side A thru Side D; white, beige and light brown wood baseboards including closets EXTERIOR - Side D; gray concrete concrete entry floor stringers and stringer caps and gray concrete entry stair treads, risers, wood door casings, headers, jambs and stops including closets EXCEPT INTERIOR - Throughout Side A thru Side D; white, beige and light brown white, beige and light brown wood window casings; headers, sills and paint chips along drip-line Room1 - Door A1, Door 5- Door C1 and Room 6 Door C1 and Room 6 Additional Clearance Tests Interior windows and floors ceiling-support beams and trim boards (Note: it is likely wood coated Side D and celling; light brown and casings have been randomly Door C1 (Note: some of the door with lead based-paint exists beneath white wood ceiling, crown moldings, NTERIOR - Room 5, Side A thru Scrape loose paint and re-paint with non-slip epoxy paint .

Cover with Tyvek and vinyl to match existing Remove paint chips and cover with landscape fabric and mulch per Risk Assesment siding Scrape loose paint and re-paint Make smooth & operable, scrape loose paint and re-paint Clean all windows and floors scrape loose paint and re-paint 3,500 SO 5/1 02% 550 こりのい

Total Cost Estimate

61300

Selective Rehab Team/Forms/Bid Forms/Led Bid Scope/Blank Jim Roy Bid Sheet